

Change Number M-41-94-02		Facility Agr Change C	control For	'm	ler	Date February 16, 1995	
Originator					Phone		
G. E. Bishop/T. E. Rainey				372-1856/373-3531			
Class of Change	unatasias	[X] II - Project	Manager	{	it Manadar		
Change Title	illacor res	Dig 11 Project	riariagei		re manage.		
Revise Schedule t	to Pump 241-BX	and BY Farm	s before 2	41-U Farm			
Description/Justification of Change							
As part of the ar have been identif							
Milestone		/2-				ate Revised Dat	
	rt Interim Sta c in 241-U Tan		f 1 Non-Wa	tch List	7/31/1	1995 8/31/1996	
	olete Interim ( in 241-U Tan		n of l Non	-Watch List	3/31/1	1996 4/30/1997	
	rt Interim Sta ch List Tanks			ble Gas	4/30/1	1996 8/31/1996	
	olete Interim ch List Tanks			mmable Gas	5/31/1	1997 9/30/1997	
(Continued p. 2)							
Impact of Change							
This change request will modify the dates of 4 interim milestones and 4 target milestones. There is no impact to the major milestone M-41-00.							
Affected Documents Hanford Federal Facility Agreement And Consent Order Action Plan, Appendix D (Table D-1 and Figure D-1 Work Schedule).							
Approvals  DOE DOUGLAND  EPA DOUGLAND	2 Shewrood	2/22/45 Date 2/22/95 Date	Approved	Disapproved			
Ecology St	only	Z.Z. 95 Date	Approved	Disapprove	d	72 24 25 26 27 28 2	
	. <u>.</u>		<del>-</del>			S FEBRUAR	

## Hanford Federal Facility Agreement and Consent Order Change Control Form M-41-94-02 Page 2

Description/Justification (cont.)

M-41-12	Start Interim Stabilization of 4 Ferrocyanide	4/30/1997	8/31/1995
	Watch List Tanks in 241-BX/BY Tank Farms.		

- M-41-12-T01 Complete Interim Stabilization of 4 Ferrocyanide 9/30/1998 12/31/1997 Watch List Tanks in 241-BX/BY Tank Farms.
- M-41-13 Start Interim Stabilization of 3 Organic Watch List 7/31/1995 8/31/1996 Tanks in 241-U Tank Farm.
- M-41-13-T01 Complete Interim Stabilization of 3 Organic Watch 12/31/1996 1/31/1998 List Tanks in 241-U Tank Farm.
- 1) The effects of interim stabilization on organic Watch List tanks containing saltcake is not completely known at this time. A strategy is being prepared to obtain the information from organic Watch List tanks required to show that removal of liquid is safe. The information may not be available in time to start pumping organic Watch List tanks in July 1995. Also one of the organic Watch List tanks scheduled to be pumped for milestone M-41-13 (241-U-107) has been added to the flammable gas Watch List since the milestone was established. The analysis providing justification to interim stabilize flammable gas tanks has not been completed and approval to pump will not happen in time to start in July 1995.
- 2) A strategy study for interim stabilization was prepared in 1994 which compared the relative risk of single-shell tanks leaking. The result of this study was that tank 241-BX-106 presented the highest risk to the environment, compared to other tanks. The total environmental risk can be significantly reduced by an early pumping of tank 241-BX-106.
- 3) The cost to interim stabilize the remaining tanks in 241-BX and BY farms will be significantly reduced if the start of interim stabilization is moved up to 1995, since it will not become necessary to re-enter the farms and bring them back to an operational status after a period of inactivity. Since pumping is currently in progress in 241-BX and BY farms, the most efficient action is to complete pumping in these tank farms.
- 4) The safety issues associated with pumping ferrocyanide tanks (241-BX/BY farms remaining tanks) have been completely resolved. This is new information since the current schedule was developed.
- 5) The pumping efficiency in 241 BY tank farm is estimated at 40% due to recent experience. The pumping efficiency in 241-U tank farm remains at 60%.